

Work Instruction Number 109 - "Workforce in Road" signs (**Relaxation Works**)
 All Amberon "Traffic Management Installations or Removals on any main road or approaching road works 40mph and above" (unless the site specific risk assessment deems it necessary on lower speeds of 40mph) must display the "Workforce in road Slow" sign, this being the 1st Sign out and last sign in.

WORKFORCE
 IN ROAD
 SLOW

TRAFFIC MANAGEMENT NOTES:
 1) All temporary traffic management shall be in accordance with Chapter 8 of the Traffic Signs Manual 2009.
 2) All temporary traffic management shall be in accordance with the Traffic Signs (Amendment) (No 2) Regulations and General Directions 2016.
 3) All temporary traffic management shall conform to the Safety at Street Works and Road Works, A Code of Practice.
 4) All temporary traffic management signs should be located 450mm min from the kerb face.
 5) All temporary traffic management sign locations are indicative and are subject to on site approval from the Engineer.

QTY: 4	REF: 7001	Road works ahead	
QTY: 4	REF: 7010-1	Nature of temporary hazard ahead - Road Ahead Closed	
QTY: 1	REF: 573	Direction to hazard (variable)	
QTY: 2	REF: 2702	Start of temporary diversion route (text)	
QTY: 2	REF: 2703	Direction of temporary diversion route from junction ahead (right)	
QTY: 2	REF: 2703	Direction of temporary diversion route from junction ahead (left)	
QTY: 1	REF: 573	Direction to hazard	
QTY: 1	REF: 2702	Start of temporary diversion route (right)	
QTY: 1	REF: 2702	Start of temporary diversion route (left)	
QTY: 4	REF: A LABEL	Road closed access only	

Phase 5

Key	
	Traffic sign
	Traffic cone/cylinder
	No waiting cone
	Pedestrian barrier
	Road closure
	Diversion route

Checked by: Jonny Barber

Customer: SSE

Job Reference: Chris Ibbotson

Location: Kingwell Rd, Boumemouth, BH10 5DG

Date: 05/06/2020

Description: Road Closure + Diversion

Scale: NTS

Amberon Ltd
 Tel: 0845 371 5050

Produced By: Vicki Wilkins
 Drawing Ref: 05/06/2020-VW-1697
 This Drawing is subject to Copyright and remains the property of Amberon Ltd.

